


Appendix B

2010 EE/CA Field Investigation

Photograph Log



Map Location and Corresponding Photograph Number in Appendix B	Description
1	Collapsed Bunkhouse at the Chicago Mine
2	Lower Adit at the Chicago Mine
3	Chicago Mine Furnace
4	Hosting Structure at the Chicago Mine
Location 5a: Not a Photograph	Vantage Point of Camera/Photographer for Photograph 5
5	Wide-shot of Ore Processing Area at the Chicago Mine
6	Partially Collapsed Bunkhouse at the Chicago Mine
7	Chicago Mine Prospect Road
8	Upper Spring Above Chicago Mine
9	Stope at Chicago Mine
10	Brick Feature at the Research Mine
11	Research Mine Collapsed Adit
12	Retaining Wall at the Research Mine Furnaces
13	Upper Standing Furnace at Research Mine
14	Collapsed Furnace at Research Mine
15	Compressor Tanks at the Research Mine
16	Lower Furnace at Research Mine
17	Compressor Tanks and Lower Adit at Research Mine
18	Ore Cart on Abandoned Mine Road at Research Mine
19	Bridge Abutment at Research Mine
Location 20a: Not a Photograph	Vantage Point of Camera/Photographer for Photograph 20
20	View of Main Access Road to Research Mine

Legend

- Photograph (See Appendix B)
- Photographer's Vantage Point
- Mine Boundaries
- Abandoned Mine Roads
- Hydrology (Dry Creek)

Notes:
 Locations for SAIC and USGS samples based on SAIC report entitled:
 Removal Site Evaluation Report, Chicago/Research Mercury Mine, July 2010.

US Department of the Interior
 Bureau of Land Management
 California State Office
 2800 Cottage Way, Suite W-1834
 Sacramento CA, 95825

ENVIRONMENTAL COST MANAGEMENT, INC.
Managing Cost and Liability
 3525 Hyland Avenue, Suite 200 Costa Mesa CA 92626
 Tel: (714) 662-2759 Fax: (714) 662-2758
 www.ecostmanage.com

**Site Features
 Chicago Research Site
 Lake County, California**
 Engineering Evaluation/Cost Analysis Report
 The Chicago Research Site

Figure
B-1

EE/CA INVESTIGATION PHOTOGRAPH LOG

(Cross-Reference Figure B-1)



Photo 1: Collapsed Processing Cabin at the Chicago Mine



Photo 2: Lower Adit at the Chicago Mine



ENVIRONMENTAL COST MANAGEMENT, INC.
Managing Cost and Liability
3525 Hyland Avenue, Suite 200 • Costa Mesa, CA 92626
Tel: (714) 662-2759 • Fax: (714) 662-2758

EE/CA Report
The Chicago Research Site
Lake County, California

Appendix B

EE/CA INVESTIGATION PHOTOGRAPH LOG
(Cross-Reference Figure B-1)



Photo No. 3: Chicago Mine Furnace



Photo No. 4: Hosting Structure at the Chicago Mine



ENVIRONMENTAL COST MANAGEMENT, INC.
Managing Cost and Liability
3525 Hyland Avenue, Suite 200 • Costa Mesa, CA 92626
Tel: (714) 662-2759 • Fax: (714) 662-2758

EE/CA Report
The Chicago Research Site
Lake County, California

Appendix B

EE/CA INVESTIGATION PHOTOGRAPH LOG
(Cross-Reference Figure B-1)




Photo No. 5
Wide-shot of Ore Processing Area at the Chicago Mine



ENVIRONMENTAL COST MANAGEMENT, INC.
Managing Cost and Liability
3525 Hyland Avenue, Suite 200 • Costa Mesa, CA 92626
Tel: (714) 662-2759 • Fax: (714) 662-2758

EE/CA Report
The Chicago Research Site
Lake County, California

Appendix B

EE/CA INVESTIGATION PHOTOGRAPH LOG
(Cross-Reference Figure B-1)



Photo No. 6: Partially Collapsed Processing Cabin at the Chicago Mine




Photo No. 7: Chicago Mine Prospect Road



ENVIRONMENTAL COST MANAGEMENT, INC.
Managing Cost and Liability
3525 Hyland Avenue, Suite 200 • Costa Mesa, CA 92626
Tel: (714) 662-2759 • Fax: (714) 662-2758

EE/CA Report
The Chicago Research Site
Lake County, California

Appendix B

EE/CA INVESTIGATION PHOTOGRAPH LOG
(Cross-Reference Figure B-1)



Photo No. 8: Upper Spring Above Chicago Mine



ENVIRONMENTAL COST MANAGEMENT, INC.
Managing Cost and Liability
3525 Hyland Avenue, Suite 200 • Costa Mesa, CA 92626
Tel: (714) 662-2759 • Fax: (714) 662-2758

EE/CA Report
The Chicago Research Site
Lake County, California

Appendix B

EE/CA INVESTIGATION PHOTOGRAPH LOG
(Cross-Reference Figure B-1)



Photo No. 9: Stope at Chicago Mine



Photo No. 10: Brick Feature at the Research Mine



ENVIRONMENTAL COST MANAGEMENT, INC.
Managing Cost and Liability
3525 Hyland Avenue, Suite 200 • Costa Mesa, CA 92626
Tel: (714) 662-2759 • Fax: (714) 662-2758

EE/CA Report
The Chicago Research Site
Lake County, California

Appendix B

EE/CA INVESTIGATION PHOTOGRAPH LOG
(Cross-Reference Figure B-1)




Photo No. 11: Research Mine Collapsed Adit



ENVIRONMENTAL COST MANAGEMENT, INC.
Managing Cost and Liability
3525 Hyland Avenue, Suite 200 • Costa Mesa, CA 92626
Tel: (714) 662-2759 • Fax: (714) 662-2758

EE/CA Report
The Chicago Research Site
Lake County, California

Appendix B

EE/CA INVESTIGATION PHOTOGRAPH LOG
(Cross-Reference Figure B-1)




Photo No. 12: Retaining Wall at the Research Mine Furnaces



ENVIRONMENTAL COST MANAGEMENT, INC.
Managing Cost and Liability
3525 Hyland Avenue, Suite 200 • Costa Mesa, CA 92626
Tel: (714) 662-2759 • Fax: (714) 662-2758

EE/CA Report
The Chicago Research Site
Lake County, California

Appendix B

EE/CA INVESTIGATION PHOTOGRAPH LOG
(Cross-Reference Figure B-1)



Photo No. 13: Upper Standing Furnace at Research Mine



ENVIRONMENTAL COST MANAGEMENT, INC.
Managing Cost and Liability
3525 Hyland Avenue, Suite 200 • Costa Mesa, CA 92626
Tel: (714) 662-2759 • Fax: (714) 662-2758

EE/CA Report
The Chicago Research Site
Lake County, California

Appendix B

EE/CA INVESTIGATION PHOTOGRAPH LOG

(Cross-Reference Figure B-1)



Photo No. 14: Collapsed Furnace at Research Mine



Photo No. 15: Compressor Tanks at the Research Mine



ENVIRONMENTAL COST MANAGEMENT, INC.
Managing Cost and Liability
3525 Hyland Avenue, Suite 200 • Costa Mesa, CA 92626
Tel: (714) 662-2759 • Fax: (714) 662-2758

EE/CA Report
The Chicago Research Site
Lake County, California

Appendix B

EE/CA INVESTIGATION PHOTOGRAPH LOG

(Cross-Reference Figure B-1)



Photo No. 16: Lower Furnace at Research Mine



Photo No. 17: Compressor Tanks and Lower Adit at Research Mine



ENVIRONMENTAL COST MANAGEMENT, INC.
Managing Cost and Liability
3525 Hyland Avenue, Suite 200 • Costa Mesa, CA 92626
Tel: (714) 662-2759 • Fax: (714) 662-2758

EE/CA Report
The Chicago Research Site
Lake County, California

Appendix B

EE/CA INVESTIGATION PHOTOGRAPH LOG

(Cross-Reference Figure B-1)



Photo No. 18: Ore Cart on Abandoned Mine Road at Research Mine



Photo No. 19: Bridge Abutment at Research Mine



ENVIRONMENTAL COST MANAGEMENT, INC.
Managing Cost and Liability
3525 Hyland Avenue, Suite 200 • Costa Mesa, CA 92626
Tel: (714) 662-2759 • Fax: (714) 662-2758

EE/CA Report
The Chicago Research Site
Lake County, California

Appendix B

EE/CA INVESTIGATION PHOTOGRAPH LOG
(Cross-Reference Figure B-1)



Photo No. 20: View of Main Access Road to Research Mine



ENVIRONMENTAL COST MANAGEMENT, INC.
Managing Cost and Liability
3525 Hyland Avenue, Suite 200 • Costa Mesa, CA 92626
Tel: (714) 662-2759 • Fax: (714) 662-2758

EE/CA Report
The Chicago Research Site
Lake County, California

Appendix B