



Photograph 1:  
View from Northwest corner of  
the site, looking East from top of  
rock wall.



Photograph 2:  
View from middle of large pile  
looking back up towards rock  
wall.



Photograph 3:  
White and grey fine material in  
mounds at large pile.



Photograph 4:  
East facing slopes of large pile.



Photograph 5:  
View from large pile toward the  
valley below (looking East).



Photograph 6:  
Sloughing of steeper slopes  
exposes white and grey fine  
material under vegetated  
surface.



Photograph 7:  
Steep slopes at large pile.  
Erosion evident above road  
cuts.



Photograph 8:  
Eroded areas in steep portions  
of large pile.



Photograph 9:  
Close up of white and grey  
material.



Photograph 10:  
Mill building located in West  
portion of site.



Photograph 11:  
Scattered debris and  
abandoned mining equipment  
found in gully below mill  
building.



Photograph 12:  
Remains of cart and tracks.



Photograph 13:  
Wooden structure located in  
West portion of site.



Photograph 14:  
Remains of mining equipment.



Photograph 15:  
Shed and bulldozer.



Photograph 16:  
View of smaller waste piles  
within Southern portion of the  
site.



Photograph 17:  
Waste material is fairly well  
revegetated in Southern  
portions of the site.



Photograph 18:  
Revegetated cover at Southern  
piles.



Photograph 19:  
Remains of brick retort.



Photograph 20:  
Wetland located in central  
portion of the site.



Photograph 21:  
Vegetation in and around  
wetland area.