



Photograph 1:
View from atop Petray North (PN)
waste rock dump looking east




Photograph 2:
View from hilltop at northern end of
site; looking north toward Deadshot
Canyon



Photograph 3:
Hole/collapse in center of PN pit;
surrounded by fine sediment
deposit; source/cause unknown



Photograph 4:
View into hole/collapse; bottom not visible



Photograph 5:
Bottom of PN pit; fine, light brown material; area appears to collect runoff from surrounding slopes



Photograph 6:
Fault line in wall of PN pit; sampled material with potential to contain higher levels of mercury



Photograph 7:
Sample of material in top/mouth of
eroding canyon at PN; looking west
(uphill)



Photograph 8:
View from top/mouth of eroding
canyon at PN; looking east
(downhill)



Photograph 9:
View of Petray South (PS) looking
south; majority of pile/dump in photo



Photograph 10:
View of PS from top (south end),
looking north



Photograph 11:
Rathburn North (RN); looking into
main pit, toward southeast



Photograph 12:
East side of RN pit; material piled
and pushed from west to east for
dumping



Photograph 13:
Scattered waste rock piles north of
pit berm pile at RN.



Photograph 14:
East dump drainage gully at RN



Photograph 15:
East dump drainage gully at RN
(field book for scale)



Photograph 16:
View from top of east dump of RN
looking east



Photograph 17:
Main pit at Rathburn South (RS)
location



Photograph 18:
Several waste rock piles at RS;
various remains of structures and
equipment scattered over site



Photograph 19:
Waste rock piles at RS displaying
successful natural revegetation
(grasses and shrubs)



Photograph 20:
Sample collection from waste rock
pile in RS area



Photograph 21:
Discovered remains of mill site
located northwest of PS area



Photograph 22:
Foundation of mill or processing structure



Photograph 23:
Waste rock piles above and below foundation remains



Photograph 24:
Remains of metal roof



Photograph 25:
Waste rock pile below mill spills into
draining gully



Photograph 26:
Top of waste rock pile at suspected
mill site



Photograph 27:
Potential borrow source material;
flat grassy meadow off site access
road



Photograph 28:
Potential borrow source material
found on north and south sides of
road at west access to site



Photograph 29:
Discovered spring northwest of
potential borrow material fields



Photograph 30:
Spring deposition on surface; hard,
yellow/orange/red solids



Photograph 31:
Spring surface effluent