



**Existing Conditions**



**Future Conditions**

Note: Transmission line is located on the north side of the valley and is obscured by atmospheric conditions.

**Summary of Visual Changes**

**Volume of Users:** Low - relatively few in number  
**T/L Distance from Viewer:** Middleground - approximately one and one-half miles from the viewpoint, but the T/L would have to be crossed to access the KOP  
**T/L Prominence in Landscape:** Low - the transmission line would be seen against distant and near background topographic features  
**Existing Modifications:** Two existing wood pole transmission lines and small building near the proposed T/L location; substantial road cut (behind this viewpoint)

**Contrast Rating:** Moderate  
**VRM Class:** IV  
**Visual Impact Rating:** Low

**KOP 8  
 Geologic Feature**

Figure 3.9-9