



Existing Conditions



Future Conditions

Summary of Visual Changes

Type/Sensitivity of Users: Residents, recreationalists

Volume of Users: Few

T/L Distance from Viewer: Middleground

T/L Prominence in Landscape: High - a tower is prominently located on the ridge top

Existing Modifications: An existing wood pole transmission line is located approximately 100 feet to the south of the proposed crossing; a number of scattered residences are located within view of the area

Contrast Rating: Moderate

VRM Class: III (Interim)

Visual Impact Rating: Medium

**KOP 28
Hercules Gap**

Figure 3.9-29

Falcon to Gonder Project EIS