



**Existing Conditions**



**Future Conditions**

Note: Proposed transmission line is located on the east side of Whirlwind Valley and is obscured by atmospheric conditions and mountain backdrop.

**Summary of Visual Changes**

**Volume of Users:** Low - relatively few  
**T/L Distance from Viewer:** Middleground - approximately one mile  
**T/L Prominence in Landscape:** Low - seen against near to distant landforms  
**Existing Modifications:** Two existing wood pole transmission lines and small building near the proposed T/L location; substantial road cut (behind this viewpoint)

**Contrast Rating:** Moderate  
**VRM Class:** IV  
**Visual Impact Rating:** Low

**KOP 2  
 Geologic Feature**

Figure 3.9-3