

Appendix A

Updates and Errata to the Final Environmental Impact Statement

Updates and Errata

Table of Contents

Pages xviii and xix

In the List of Tables, the tables for Sections 3.7 and 3.8 are missing the hyphen in the table number (for example: Table 3.7 1, rather than Table 3.7-1). These should all have hyphens in the table number.

Section 1.0

Page 1-12: The URLs for the following NRC documents are now:

Source and Byproduct Material License

<http://adams.nrc.gov/wba/>

Under Advanced Search, Document Properties, Accession Number ML111940049

Safety Evaluation Report

<http://adams.nrc.gov/wba/>

Under Advanced Search, Document Properties, Accession Number ML112231724

Section 1.4.3: add the following paragraph

Since the publication of the EIS, LCI has indicated an intent to develop the LC East Area. Because LCI has not prepared or submitted a proposed plan modification to BLM, there is insufficient information to address this expansion in this Final EIS, as the development extent is speculative at this time. Any development activity in this area would be covered by a separate NEPA analysis and decision. Development of the LC East Area was appropriately considered in the Cumulative Effects section of this Final EIS.

Section 2.0

Pages 2-57 through 2-61:

In the header row of Table 2.2-1, the WDEQ-LQD Permit No. should be “788” rather than “766.”

Table 2.2-2:

Add the following row to the table:

Resource	Aspect	Description of Measures
Transportation	Roads	LCI will obtain a Road Use and Maintenance Agreement from the BLM for any crossing, access to, or use of a BLM-controlled road outside the permit boundary.

Section 3.3

Page 3.3-11:

On bottom of the page, part of the sentence is missing. It should read: "a major paleochannel. The mineralization occurs as both roll front and tabular deposits."

Section 4.7

Page 4.7-30:

The liner material thickness will be about 40 mils, not 41 millimeters (approximately 1,600 mils).

Section 4.9

Pages 4.9-41 and 4.9-42:

There are two incorrect line returns in Section 4.9.6.5. The Table number after these incorrect returns should be bold.

Section 4.18

Page 4.18-7:

This section discusses the storage and handling of solid 11(e)(2) byproduct materials. The sentence saying "The materials would be temporarily stored on-site in containers called 'super-sacs'" should be edited to include strong tight containers as a storage method for these materials.

Section 8.0

Page 8-21

There is a vertical line on the right side of the page above the Reed, 1988 reference. This line should be removed.

Glossary

Page G-7:

The term "pump test" is listed twice. The second definition is more descriptive. In the first sentence of the definition, "form" should be "from".

Appendix F

Page F-38:

The response at the top of the page states that lek count data has been added to Table 3.8-3 in the FEIS. This table that was updated is Table 3.8-4, and the text should be corrected to reflect this.