


# 2011 BLM Safecomms

## Total 2011 Safecomms


- 921

## Total BLM Safecomms

- 115




# 2011 BLM SAFECOMS




# 2011 BLM Safecomms


## By State (115)



# 2011 BLM Safecomms by Aircraft Type



# FY 05-11 BLM Safecomms



Total Flt Hrs.	30339	32173	28099	18501	17453	19862	17236
RW	12269.8	10410	9957	6404	6589	8831	6227
FW	18068.9	13719	11211	6916	7432	8527	8643
SEAT	Included w/FW	8044	6581	4921	1817	1493	2366

# 2011 BLM Elevated Safecoms

- 11-0847 Saw File tossed into rotor system.
  - HECM noticed a loose saw file in the expanded metal bottom of the external basket; the file was tossed away from the AS-350B2 helicopter while the blades were turning impacting the leading edge of one main blade.



# 2011 BLM Elevated Safecoms

- 11-0808 Water Drop on firefighters
  - Helitanker drop impacted three firefighters during line construction. Two injuries occurred. Poor communication between aircraft and ground firefighters.

