

Submit Form To:

Amarillo Field Office
ATTN: Assistant Field Manager for Operations
801 S. Fillmore, Suite 500
Amarillo, TX 79101

Cliffside Gas Plant Status Report

Date & Time of Outage: October 15, 2016 at 0800 (CDT)

Cause of Outage: Scheduled outage for annual maintenance and repairs.

Factors Causing Restart:

- Scheduled outage.

Current Status:

- 1000 (CDT), Tuesday, October 25, 2016 – plans are to uncover Run Zero piping to locate leak and make preparations for repair or interim patching.

Forecast:

- Producing 1908 Mscf/d of helium into the Helium Conservation Pipeline. System will be monitored and flow will increase after repair to Run Zero.

Pipeline Pressure at Cliffside: At 1000 (CDT), Tuesday, October 25, 2016 = 867 psig

Next Report: 1530 (CDT), Tuesday, October 25, 2016

Points of Contact:

Sam Burton, Acting Field Manager at 806-683-7726, sburton@blm.gov, or
Wesley W. Ingram, Acting AFM-HE Ops at 806-356-1023, wingram@blm.gov