

**Submit Form To:**

Amarillo Field Office  
ATTN: Assistant Field Manager for Operations  
801 S. Fillmore, Suite 500  
Amarillo, TX 79101

---

**Cliffside Gas Plant Status Report**

**Date & Time of Outage:** October 15, 2016 at 0800 (CDT)

**Cause of Outage:** Scheduled outage for annual maintenance and repairs.

**Factors Causing Restart:**

- Scheduled outage.

**Current Status:**

- 0930 hours, Monday, October 17, 2016 – Pipeline pressure was 1273.6 psig at 0658 hours. Multiple contractors are onsite. Enerflex has collected their parts and preparing to perform maintenance on the chiller. Air Products is engaged in the repairs on the Cold Flash Tank. Praxair, Mark Carey, and ArchRock have staged for the maintenance on the K-610 and preparing for maintenance on the K-100 and K-600. Header replacement project is underway with several of the wells connected to the new header. Scaffolding is in place for cleaning the fin fan exchangers. There is a water supply of 6000 gallons available with another 2500 gallons in reserve.
- 1030 hours, Monday, October 17, 2016 – the reboiler gas supply is being hydraulically balanced between the burners to provide the same flow to both burners. The electrical work on the Cold Flash Tank is going well.

**Forecast:**

- Continue maintenance and repairs with current plans to initiate start-up operations late on October 21, 2016.

**Pipeline Pressure at Cliffside:** At 0658 (CDT), Monday, October 17, 2016 = 1273.6 psig

Pressure at 1500 hours was not available as testing of electrical systems required the power to be off.

**Next Report:** Tuesday, October 18, 2016 at 0900 (CDT)

**Points of Contact:**

Sam Burton, Acting Field Manager at 806-683-7726, [sburton@blm.gov](mailto:sburton@blm.gov), or  
Wesley W. Ingram, Acting AFM-HE Ops at 806-356-1023, [wingram@blm.gov](mailto:wingram@blm.gov)