

Submit Form To:

Amarillo Field Office
ATTN: Assistant Field Manager for Operations
801 S. Fillmore, Suite 500
Amarillo, TX 79101

Cliffside Gas Plant Status Report

Date & Time of Outage: October 15, 2016 at 0800 (CDT)

Cause of Outage: Scheduled outage for annual maintenance and repairs.

Factors Causing Restart:

- Scheduled outage.

Current Status:

- 1030 hours, Tuesday, October 18, 2016 – Pipeline pressure was 1194 psig at 0658 hours. Reboiler gas supply project completed. Compressor maintenance on K-100, K-600 and K-610 continues. Chiller preventative maintenance underway. Fin fans are being cleaned. Header and pig launcher piping replacements are progressing.

Forecast:

- Continue maintenance and repairs with current plans to initiate start-up operations late on October 21, 2016.

Pipeline Pressure at Cliffside: At 0658 (CDT), Tuesday, October 18, 2016 = 1294 psig

Pressure is decreasing at approximately 80 psig per day. Allocation estimated approximately 65 psig per day.

Next Report: Tuesday, October 19, 2016 at 0830 (CDT)

Points of Contact:

Sam Burton, Acting Field Manager at 806-683-7726, sburton@blm.gov, or
Wesley W. Ingram, Acting AFM-HE Ops at 806-356-1023, wingram@blm.gov