
Elk Creek Road Culvert Replacement and Detour





US DEPARTMENT OF THE INTERIOR Bureau of Land Management



Coos Bay District Office Myrtlewood Field Office 1300 Airport Lane North Bend, OR 97459



o warranty is made by the Bureau of Land Management as to the accuracy, liability, or completeness of these data for individual or aggregate use ith other data. Original data were compiled from various sources and may undated without postferation.