

CORPS OF ENGINEERS
INFORMATION NOTICE

- No surface occupancy for that portion of the lease area subject to inundation, lying below contour elevation 1855 feet msl (mean sea level).
- All existing boundary fencing must be maintained in its current location.
- All existing access roads must be maintained in a safe and usable condition at all times.
- In the event that directional drilling is contemplated, all facilities constructed on project lands which can be damaged by flood water and which cannot be readily moved if a flood is imminent, must be constructed from a location approved by the District Engineer. The location must be above or adequately protected by a dike enclosure to an elevation to be determined at the time of drilling, plus the additional height determined necessary to protect against windwave runup and overtopping.
- There are numerous identified archaeological sites within portions of the lease areas, therefore all activities must be coordinated with the Corps of Engineers Archaeologist located at the Garrison Dam/Lake Sakakawea Project Office.