


No warranty is made by the Bureau of Land Management as to the accuracy, reliability, or completeness of these data for individual or aggregate use with other data. Original data were compiled from various sources. This information may not meet National Map Accuracy Standards. This product was developed through digital means and may be updated without notification.



Legend

- Water Quality Monitoring Site
- 303d Stream
- Fourth-Field Subbasin Boundary
- Proper Functioning Condition Rating**
- Proper Functioning Condition
- Functional At Risk- Upward Trend
- Functional At Risk- Downward Trend
- Functional At Risk- Trend Not Apparent
- Non-Functional
- Other Perennial River or Stream
- Planning Area Boundary
- Baker Resource Area Boundary
- Administered Land**
- Bureau of Land Management
- BLM Land Outside Planning Area
- US Forest Service
- US Department of Defense
- Bureau of Reclamation
- Other Federal
- State
- Private or Other
- Umatilla Indian Reservation



U.S. DEPARTMENT OF THE INTERIOR
 Bureau of Land Management
VALE DISTRICT
 BAKER RESOURCE AREA
 RESOURCE MANAGEMENT PLAN REVISION
 ANALYSIS OF THE MANAGEMENT SITUATION
 2009

Map 2.2

Map 2.2- Baker Planning Area Fourth-Field Sub-Basins and Water Quality