

**INSPECTION PHOTOS**  
**Interagency State Office**  
**Page 1 of 2**

---



Heater plugged into power tap extension



Boxes stored on tall cabinets – not secure



Common area used as storage site



Housekeeping needed to eliminate hazards



Common area used as storage site



Example of a well-kept work area


**INSPECTION PHOTOS**  
**Interagency State Office**  
**Page 2 of 2**



Paint can and pail stored in work area




Open pail with brush



Coffee pot plugged into power strip



Use of extension cord



Two power cords plugged together



Work area used as storage

**INSPECTION PHOTOS**  
**Interagency Warehouse**  
**Page 1 of 1**



Electrical panel access impeded




Panel access rearranged and taped



Storage racks not secured to each other and wall



a correctly-signed flammable storage cabinet



Warehouse well organized/excellent housekeeping



Heavy forklift appropriately guarded

**INSPECTION PHOTOS**  
**Northwest Coordination Center (NWCC)**  
Page 1 of 1

---



Insecticide stored under sink in kitchen area



Power strips plugged together




Electrical panel access blocked by boxes



Power strips plugged together in work area



Insecticide spray can on floor in work area



Power strip used for shredder and vacuum