

MOUNTAIN OF THE ROGUE RECONSTRUCTION



An excavator works on repairing the PB&J Trail after the North River Road Fire.



Check out the flow on the new section of the PB&J trail.




The PB&J Trail needed significant work to bring back ideal riding conditions.



Features like berms, pictured here, draw riders from all over and provide opportunities for beginner to advance riders enjoy the trails at Mountain of the Rogue.



A section of the Pay Dirt trail after the North River Road Fire.



Riders can now enjoy a smooth section of the Pay Dirt trail, with great views!



Damage to the Rat Pack Trail



BLM employees and contractors helped rebuild the Rat Pack Trail at Mountain of the Rogue.



A BLM employee checks for ideal flow. Come check out the Mountain of the Rogue, we have it dialed back in!