

Book Cliffs Range Improvements Sand Wash Allotment

RIPS #	Allotment	Type	Cooperative Agreement	Project	Location	Notes
0073	UT08818	Corral	Yes	Cottonwood Corral	T12S,R21E,sec.3,NWSW	old corral, needs work
0273	UT08819	Reservoir	Yes	West Cottonwood Reservoir	T11S,R21E,sec.5,NWSE	needs a recent inspection
4012	UT08820	Well	Yes	Cottonwood Wash Well	T11S,R21E,sec.21,NESW	well pump needs to be addressed needs to be cleaned and is within land exchange acreage
4430	UT08821	Reservoir	Yes	Twelve mile Knoll Reservoir	T11S,R21E,sec.01,NWSW	
4456	UT08822	Reservoir	Yes	West Bench Reservoir	T11S,R21E,sec.17,SWNW	needs a recent inspection
4509	UT08823	Reservoir	Yes	Meagher Reservoir #3/#2	T11S,R21E,sec.21,NESW	RIP, needs a recent inspection
4680	UT08824	Guzzler	o Coop Needed BLM/DW	Sand Wash Guzzler	T11S,R21E,sec.23,NENW	*Wildlife Guzzler - no agreement needed
4703	UT08825	Reservoir	No	Uintah Badlands Well/Res #1	T11S,R21E,sec.7,SWNE	needs a recent inspection
4704	UT08826	Reservoir	Yes	Sand Wash Allot Res #1	T10S,R21E,sec.21,SESE	needs a recent inspection
4705	UT08827	Reservoir	Yes	Uintah Badlands Well/Res #2	T10S,R20E,sec.35,NWNW	needs a recent inspection
4707	UT08828	Reservoir	Yes	Sand Wash Allot Res #2	T10S,R21E,sec.23,SWSE	needs a recent inspection
4708	UT08829	Reservoir	Yes	Sand Wash Allot Res #3	T10S,R21E,sec.26,SWSE	needs a recent inspection
4709	UT08830	Reservoir	Yes	Sand Wash Allot Res #4	T10S,R21E,sec.35,SWNE	needs a recent inspection
4710	UT08831	Reservoir	Yes	Sand Wash Allot Res #5	T10S,R21E,sec.14,SWSW	needs a recent inspection
4712	UT08832	Reservoir	Yes	Sand Wash Allot Res #7	T10S,R21E,sec.3,NWNE	needs a recent inspection
4713	UT08833	Reservoir	Yes	Sand Wash Allot Res #8	T10S,R21E,sec.7,SWSW	needs a recent inspection
4767	UT08834	Reservoir	o Coop Needed BLM/DW	Middle Bench Antelope Guzzler	T11S,R21E,sec.26,SESE	*BLM wildlife project, needs a recent inspection
4768	UT08835	Guzzler	o Coop Needed BLM/DW	Cottonwood Wash Ant Guzzler	T11S,R21E,sec.28,NWNW	*BLM wildlife project, needs a recent inspection
4780	UT08836	Guzzler	o Coop Needed BLM/DW	Cotton Antelope Guzzler	T11S,R22E,sec.7,SWSE	*BLM wildlife project, needs a recent inspection
4801	UT08837	Guzzler	o Coop Needed BLM/DW	North Cottonwood Antel Guzzler	T11S,R22E,sec.4,NWSW	*BLM wildlife project, needs a recent inspection *Large project permittee, BLM and Tribe were original cooperators
4953, 4994	UT08838	Fence	Yes	Natural Buttes W Bench Fence	T10S,R20E,sec.11,NWNW	
8029	UT08839	Reservoir	Yes	Dusty Reservoir	T10S,R20E,sec.12,NWNW	needs cleaned last inspected 2010
8067	UT08840	Reservoir	Yes	Dusty Pond	T10S,R20E,sec.11,NENE	needs cleaned last inspected 2010
8068	UT08841	Reservoir	Yes	Seep Ridge Reservoir	T10S,R20E,sec.12,SWSW	needs cleaned last inspected 2010
8069	UT08842	Reservoir	Yes	Mini Sandwash Pond	T10S,R20E,sec.12,NWSW	needs cleaned last inspected 2010
8070	UT08843	Reservoir	Yes	Mini Sandwash Pond #2	T10S,R20E,sec.12,SWNW	needs cleaned last inspected 2010

* Project List Acknowledged at Attachment A for Form 4120-6 Bureau of Land Management Cooperative Improvement Agreement; projects highlighted are not included in this Cooperative