

Book Cliffs Range Improvements Atchee Ridge AMP

RIPS #	Allotment	Type	Cooperative		Project	Location	Built
			Notes	Agreement			
0009	08824	Fence	needs recent inspection may be removed	No	Anderson Drift fence	T11s R25e S27 sub sesw	RIP 1944
0014	08824	Fence	good fence	Yes	Davis canyon fence	T14s R26e S6 Sub nwse	1962
0018	08824	Fence	good fence	Yes	Boulevard ridge fence	T13s R25e S17 Sub nenw	1962
0030	08824	Water/Control	needs recent inspection	Yes	Hill & Havens Reservoir	T13s R25e S22 Sub ssw	1951
0184	08824	Exclosure	coop not necessary BLM/DWR project,	Yes	Big Park Study plot	T13s R24e S3 Sub nwse	1964
0187	08824	Exclosure	coop not necessary BLM/DWR project,	Yes	Atchee Ridge Study	T13s R25e S4 Sub nwne	1964
0210	08824	Water/Control	needs recent inspection	Yes	Burnt point #2	T14s R25e S35 Sub nsw	1945
0213	08824	Water/Control	needs recent inspection	Yes	Burnt point spring	T14s R25e S28 Sub sese	1945
0320	08824	Vegetation manipulation	coop not necessary	No	Moonshine browse control	T13s R25e S26 Sub	1968 Chaining
0354	08824	Management Facility	coop not necessary	No	Atchee Ridge Road	T14s R26e S2 Sub senw	1950
0355	08824	Fence	needs recent inspection	Yes	Gentry Fence	T12s R25e S18 Sub nenw	1950
0459	08824	Fence	needs recent inspection	Yes	Stringham Cons. Cont fence	T11s R25e S27 Sub sese	1961
4013	08824	Fence	needs recent inspection	Yes	Saddle Post-Pk Can. Fence	T11s R25e S7 Sub	1970
4033	08824	Fence	needs recent inspection	Yes	BLVD Ridge Reservoir	T13s R25e S17 Sub nese	1970
4034	08824	Water/Control	needs recent inspection	Yes	BLVD Ridge Reservoir west	T13s R25e S17 Sub	1970
4037	08824	Fence	coop not necessary	No	BLVD Study Fence	T13s R25e S16 Sub w	1971
4101	08824	Fence	needs recent inspection	Yes	Bitter Creek Fence	T15s R26e S18 Sub	1976
4171	08824	Water/Control	needs a new trough, BLM rebuilt spring exclosure in 2011	Yes	Lee Canyon spring	T15s R26e S19 Sub nwnw	1977
4184	08824	Water/Control	needs a recent inspection	Yes	Dick Canyon Springs	T15s R25e S23 Sub nsw	1977
4190	08824	Fence	needs a recent inspection	Yes	Chaining Fire fence	T13s R25e S19 Sub se	1978
4247	08824	Water/Control	coop not necessary	No	USGS Stream Gauges	T12s R25e S1 Sub ssw	1998
4251	08824	Water/Control	coop not necessary	No	USGS Stream Gauges	T15 R 25 S13 Sub nwnw	1998
4290	08824	Water/Control	coop not necessary BLM/DWR project,	No	Rat Hole RDGE GUZ #1	T142 R25e S34 Sub swnw	1981
4291	08824	Water/Control	coop not necessary BLM/DWR project,	No	Rat Hole RDGE GUZ #2	T14s R25e S25 Sub sesw	1981
4344	08824	Vegetation manipulation	coop not needed BLM project	No	Lone Spring Ridge RX burn	T13s R24e S23 Sub s2se	1982
4462	08824	Water/Control	needs inspection after cleaning	Yes	Atchee Ridge Res #1	T13s R25e S7 Sub nene	1957
4463	08824	Water/Control	needs inspection after cleaning	Yes	Atchee Ridge Res #2	T13s R24e S1 Sub ssw	1957
4464	08824	Water/Control	needs inspection after cleaning	Yes	Atchee Ridge Res #3	T13s R25e S8 Sub nenw	1952
4465	08824	Water/Control	needs inspection after cleaning	Yes	Atchee Ridge Res #4	T13s R24e S4 Sub nenw	1982
4466	08824	Water/Control	needs inspection after cleaning	Yes	Atchee Ridge Res #5	T13s R25e S5 Sub senw	1982
4508	08824	Water/Control	needs some work as of last inspection 2011	Yes	Rector Ridge Guzzler	T12s R25e S33 Sub nwne	1982
4553	08824	Water/Control	needs an inspection and water right and property ownership checked	Yes	Lone spr pplne & devel	T14s R25e S13 Sub sw	1983
4554	08824	Management Facility	no coop needed BLM/Uintah County	No	Dick Canyon CG	T15s R25e S10 Sub nwse	1983
4557	08824	Water/Control	needs a recent inspection	Yes	Indian SPG pipeline	T13s R25e S20 Sub s2	1983
4560	08824	Water/Control	needs a recent inspection	Yes	East tent spring	T14s R25e S12 Sub nsw	1983
4603	08824	Management Facility	needs rebuilt	Yes	Moonshine Corral	T14s R25e S9 Sub ne	1967
4605	08824	Fence	needs a recent inspection	Yes	Dick Canyon Fence	T15s R25e S10 Sub se	1982
4606	08824	Water/Control	needs inspection after cleaning	Yes	Atchee Ridge Res #6	T13s R25e S27 Sub nenw	1983
4607	08824	Water/Control	needs inspection after cleaning	Yes	Atchee Ridge Res #7	T13s R25e S27 Sub nene	1983
4608	08824	Water/Control	needs inspection after cleaning	Yes	Atchee Ridge Res #8	T13s R25e S26 Sub swse	1983
4609	08824	Water/Control	needs inspection after cleaning	Yes	Atchee Ridge Res #9	T13s R25e S35 Sub nwne	1983
4625	08824	Water/Control	no coop necessary	No	Augusi Cyn ESRN Dams	T13s R25e S27 Sub ssw	1983
4641	08824	Vegetation manipulation	no coop necessary	No	Agusi Canyon RX Burn	T14s R25e S8 Sub	1984
4647	08824	Water/Control	no coop necessary	No	Tent Canyon Erosion Control Dam	T14s R25e S11 Sub swse	1983
4649	08824	Water/Control	needs a recent inspection	Yes	Atchee Ridge Res #10	T13s R25e S21 Sub nese	1983
4650	08824	Water/Control	needs a recent inspection	Yes	Atchee Ridge Res #11	T13s R25e S27 Sub swne	1983
4651	08824	Water/Control	needs a recent inspection	Yes	Atchee Ridge Res #12	T13s R25e S27 Sub senw	1983
4652	08824	Water/Control	needs a recent inspection	Yes	Atchee Ridge Res #13	T13s R25e S26 Sub swnw	1983
4653	08824	Water/Control	needs a recent inspection	Yes	Atchee Ridge Res #14	T13s R25e S26 Sub nsw	1983
4654	08824	Water/Control	needs a recent inspection	Yes	Atchee Ridge Res #15	T14s R26e S6 Sub ssw	1983
4655	08824	Water/Control	needs a recent inspection	Yes	Atchee Ridge Res #16	T14s R25e S1 Sub nwse	1983
4669	08824	Water/Control	needs work - BLM/DWR may assist	Yes	Boulevard Guzzler	T13s R24e S24 Sub nese	1984
4673	08824	Water/Control	good water needs checked	Yes	Moonshine spring	T13s R25e S34 Sub nesw	1984
4675	08824	Water/Control	good water needs checked	Yes	Augusi Spring	T13s R25e S34 Sub nwnw	1984
4679	08824	Management Facility	no coop necessary	No	Evacuation Cattle Guard	T11s R25e S28 Sub nenw	1984

4681	08824	Water/Control	needs a recent inspection	Yes	Hill & Havens Reservoir #2	T13s R25e S28 Sub nene	1951
4682	08824	Water/Control	needs a recent inspection	Yes	Hill & Havens Reservoir #3	T14s R25e S1 Sub nwse	1951
4683	08824	Water/Control	needs a recent inspection	Yes	Hill & Havens Reservoir #4	T14s R26e S7 Sub nwnw	1951
4684	08824	Water/Control	no coop necessary	No	Johns Ridge Guzzler	T15s R25e S22 Sub nwnw	1984
4686	08824	Fence	needs a recent inspection	Yes	Moonshine Fence	T14s R25e S4 Sub ne	1965
4691	08824	Water/Control	needs a recent inspection	Yes	Atchee Ridge Res #17	T13s R25e S7 Sub nese	1983
4692	08824	Water/Control	needs a recent inspection	Yes	Dick canyon spring lower	T15s R25e S23 Sub nesw	1982
4694	08824	Fence	reevaluate need for fence	Yes	Tent Canyon Div Fence	T5s R104w S 30 Sub sw	1941
4698	08824	Water/Control	needs recent check for flow	Yes	Section two Spring	T15s R25e S2 Sub swse	1984
4721	08824	Water/Control	coop with DWR/BLM	Yes	John Ridge Guzzler #2	T15s R25e S16 Sub senw	1984
4735	08824	Water/Control	needs a recent inspection	Yes	Atchee ridge res #18	T13s R25e S9 Sub ssw	1984
4736	08824	Water/Control	needs water flow checked	Yes	Hands Spring	T15s R25e S15 Sub nwnw	1985
4737	08824	Water/Control	needs a recent inspection	Yes	Rector Spring Res	T13s R25e S4 Sub nwne	1985
4738	08824	Water/Control	needs a recent inspection	Yes	Three mile Spring Reservoir	T13s R25e S5 Sub nese	1984
4739	08824	Water/Control	dry last visit	Yes	Flat rock Spring	T13s R25e S17 Sub nennw	1984
4744	08824	Vegetation manipulation	no coop necessary	No	Rector Ridge Burn	T13s R25e S4 Sub	1985
4745	08824	Management Facility	no coop necessary	No	Long draw cattleguard	T12s R 24e S15 Sub sese	1985
4746	08824	Vegetation manipulation	no coop necessary	No	John's Ridge Rx burn	T15s R25e S22 Sub	1985
4760	08824	Vegetation manipulation	no coop necessary	No	Indian Spring Burn	T13s R25e S21 Sub	1985
4784	08824	Water/Control	no coop necessary	No	Indian Spring Erosion control	T13s R25e S21 Sub swse	1986
4792	08824	Water/Control	needs work	Yes	Moon Shine Ridge Guzzler	T14s R25e S15 Sub nennw	1986
4793	08824	Management Facility	good	Yes	Atchee Fence & Cattle Guard	T13s R25e S16 Sub nennw	1986
4810	08824	Water/Control	dry last visit	yes	Asphalt Spring	T13s R25e S5 Sub nennw	1986
4812	08824	Vegetation manipulation	no coop necessary	yes	Dragon Canyon Prescribed Burn	T14s R25e S33 Sub w2e2	1986
4860	08824	Water/Control	dry last visit	Yes	Mary wapinas Spring	T15s R25e S4 Sub nene	1987
4861	08824	Water/Control	dry last visit	Yes	Natchits Spring	T15s R25e S3 Sub swne	1987
4862	08824	Management Facility	no coop necessary	No	Boulevard ridge cattle guard	T13s R25e S17 Sub nws	1987
4863	08824	Water/Control	needs a recent inspection	Yes	Davis canyon ridge reservoir	T14s R25e S1 Sub senw	1987
4866	08824	Water/Control	very little water flow last visit	Yes	Boulevard spring	T13s R25e S18 Sub nese	1987
5034	08824	Water/Control	not in compliance last visit	Yes	South Rat hole Spring	T14s R25e S36 Sub senw	1989
5035	08824	Water/Control	dry last visit	Yes	Fatty canyon springs	T15s R26e S6 Sub nwnw	1989
5058	08824	Vegetation manipulation	no coop necessary	No	Davis Canyon Ridge Burn	T14s R25e S1 Sub n2	1988
5067	08824	Water/Control	good condition last inspection	Yes	Big park reservoir #1	T13s R24e S12 Sub nennw	1990
5068	08824	Water/Control	good condition last inspection	Yes	Big park Reservoir #2	T13s R24e S3 Sub nwse	1990
5069	08824	Water/Control	good condition last inspection	Yes	Big park Reservoir #3	T13s R24e S4 Sub swne	1990
5070	08824	Water/Control	good condition last inspection	Yes	Big Park reservoir	T13s R24e S6 Sub nene	1990
5136	08824	Vegetation manipulation	no coop necessary	No	Dry Burn Cny RX	T13s R25e S28 Sub e2	1986
5137	08824	Vegetation manipulation	no coop necessary	No	Atchee ridge cyn RX	T13s R25e S14 Sub w2	1986
5138	08824	Vegetation manipulation	no coop necessary	No	Rat hole cyn RX	T14s R25e S15 Sub W2w2	1980
5232	08824	Fence	needs a recent inspection	Yes	Co-ut Book Cliff Bndry Fence	T13s R25e S26 Sub sesw	1994
5252	08824	Water/Control	marginal flow 2012	Yes	So moccasin trail Sp	T15s R25e S19 Sub nene	1979
5254	08824	Fence	needs inspection	Yes	Bitter Creek gap Fence	T14s R25e S3 Sub	1995
008209	08824	Vegetation manipulation	no coop necessary BLM/DWR	No	Moonshine Ridge burn	T13s R25e S3 Sub	1983
008217	08824	Management Facility	no coop necessary BLM/DWR	No	Massey Jet Adm corral	T13s R25e S8 Sub	1977
008547	08824	Water/Control	no coop necessary BLM/DWR	No	Rathole Guzzler #3	T14s R26e S28 Sub ssw	1986