

Kern County Fire Department



Evidence and Photographic

Case: 16-22831

Arson Investigation Unit

LOCATION INFORMATION

Number	Dir	Street Name	Type	Unit ID	Unit	City	County	State
		Erskine Creek	Road			Unincorporated	Kern	CA
Unincorporated Area		Description						
Lake Isabella		BLM Lease number CACA 18073						

Reporting Investigator (b) (6), (b) (7) (C), Captain
--

EVIDENCE AND PHOTOGRAPHIC INFORMATION

Evidence (Numeric)	Photo (Alpha)	Description of Evidence or Photograph	Format Digital	Date Collected
	A	Overall Scene from the west	<input checked="" type="checkbox"/>	6/24/2016
	B	General Origin Area (GOA) outside perimeter from the north	<input checked="" type="checkbox"/>	6/24/2016
	C	GOA outside perimeter from the Northwest	<input checked="" type="checkbox"/>	6/24/2016
	D	GOA outside perimeter from the east	<input checked="" type="checkbox"/>	6/24/2016
	E	GOA outside perimeter from the north	<input checked="" type="checkbox"/>	6/24/2016
	F	GOA outside perimeter from the east	<input checked="" type="checkbox"/>	6/24/2016
	G	GOA outside perimeter from the east	<input checked="" type="checkbox"/>	6/24/2016
	H	GOA outside perimeter from the Southeast	<input checked="" type="checkbox"/>	6/24/2016
	I	GOA outside perimeter from the Southeast	<input checked="" type="checkbox"/>	6/24/2016
	J	GOA outside perimeter from the east	<input checked="" type="checkbox"/>	6/24/2016
	K	GOA outside perimeter from the Southwest	<input checked="" type="checkbox"/>	6/24/2016
	L	GOA outside perimeter from the north	<input checked="" type="checkbox"/>	6/24/2016
	M	GOA outside perimeter from the Southeast	<input checked="" type="checkbox"/>	6/24/2016
	N	GOA outside of inside perimeter from the Southeast	<input checked="" type="checkbox"/>	6/24/2016
	O	GOA outside of inside perimeter from the south	<input checked="" type="checkbox"/>	6/24/2016
	P	GOA outside of inside perimeter from the Southwest	<input checked="" type="checkbox"/>	6/24/2016
	Q	GOA outside of inside perimeter from the east	<input checked="" type="checkbox"/>	6/24/2016
	R	GOA outside of inside perimeter from the Northwest	<input checked="" type="checkbox"/>	6/24/2016
	S	GOA outside of inside perimeter from the Northwest	<input checked="" type="checkbox"/>	6/24/2016
	T	GOA outside of inside perimeter from the east	<input checked="" type="checkbox"/>	6/24/2016

Case: 16-22831**EVIDENCE AND PHOTOGRAPHIC INFORMATION**

Evidence (Numeric)	Photo (Alpha)	Description of Evidence or Photograph	Format Digital	Date Collected
	U	GOA outside of inside perimeter from the east	<input checked="" type="checkbox"/>	6/24/2016
	V	GOA outside of inside perimeter from the east	<input checked="" type="checkbox"/>	6/24/2016
	W	GOA outside of inside perimeter from the south	<input checked="" type="checkbox"/>	6/24/2016
	X	GOA outside of inside perimeter from the Southwest	<input checked="" type="checkbox"/>	6/24/2016
	Y	GOA outside of inside perimeter from the Southeast	<input checked="" type="checkbox"/>	6/24/2016
	Z	GOA outside of inside perimeter from the south	<input checked="" type="checkbox"/>	6/24/2016
	A1	GOA outside of inside perimeter from the west	<input checked="" type="checkbox"/>	6/24/2016
	B1	GOA outside of inside perimeter from the Northwest	<input checked="" type="checkbox"/>	6/24/2016
	C1	GOA outside of inside perimeter from the Northwest	<input checked="" type="checkbox"/>	6/24/2016
	D1	GOA outside of inside perimeter from the Northwest	<input checked="" type="checkbox"/>	6/24/2016
	E1	GOA fire pit inside of perimeter flagging from Northwest	<input checked="" type="checkbox"/>	6/24/2016
	F1	GOA outside of inside perimeter from the north	<input checked="" type="checkbox"/>	6/24/2016
	G1	GOA outside of inside perimeter from the Northeast	<input checked="" type="checkbox"/>	6/24/2016
	H1	GOA outside of inside perimeter from the Northeast	<input checked="" type="checkbox"/>	6/24/2016
	I1	GOA outside of inside perimeter from the north	<input checked="" type="checkbox"/>	6/24/2016
	J1	GOA outside of inside perimeter from the Northeast	<input checked="" type="checkbox"/>	6/24/2016
	K1	GOA outside of inside perimeter from the Northeast	<input checked="" type="checkbox"/>	6/24/2016
	L1	GOA outside of inside perimeter from the Northeast	<input checked="" type="checkbox"/>	6/24/2016
	M1	GOA outside of inside perimeter from the north	<input checked="" type="checkbox"/>	6/24/2016
	N1	GOA outside of inside perimeter from the Northeast	<input checked="" type="checkbox"/>	6/24/2016
	O1	GOA inside perimeter from the east	<input checked="" type="checkbox"/>	6/24/2016
	P1	Power pole P-1 Southeast of the playground from the Southwest	<input checked="" type="checkbox"/>	6/24/2016
	Q1	Power pole P-2 south of the playground from the south	<input checked="" type="checkbox"/>	6/24/2016
	R1	GOA outside of inside perimeter from the west	<input checked="" type="checkbox"/>	6/24/2016
	S1	GOA outside of inside perimeter from the Southwest	<input checked="" type="checkbox"/>	6/24/2016
	T1	Main structure on the property from the west	<input checked="" type="checkbox"/>	6/25/2016
	U1	P-1 close up panel Southeast of the playground from the west	<input checked="" type="checkbox"/>	6/25/2016
	V1	P-1 close up panel Southeast of the playground from the west	<input checked="" type="checkbox"/>	6/25/2016
	W1	P-1 zoom panel Southeast of the playground from the west	<input checked="" type="checkbox"/>	6/25/2016

Case: 16-22831**EVIDENCE AND PHOTOGRAPHIC INFORMATION**

Evidence (Numeric)	Photo (Alpha)	Description of Evidence or Photograph	Format Digital	Date Collected
	X1	P-1 zoom main breaker Southeast of the playground from the west	<input checked="" type="checkbox"/>	6/25/2016
	Y1	P-2 south of the playground panel close up from the south	<input checked="" type="checkbox"/>	6/25/2016
	Z1	P-2 south of the playground panel close up from the south	<input checked="" type="checkbox"/>	6/25/2016
	A2	P-2 south of the playground panel zoom from the south	<input checked="" type="checkbox"/>	6/25/2016
	B2	P-2 south of the playground extension cord from the south	<input checked="" type="checkbox"/>	6/25/2016
	C2	Extension cord close up male end from the south	<input checked="" type="checkbox"/>	6/25/2016
	D2	Extension cord from the Southeast	<input checked="" type="checkbox"/>	6/25/2016
	E2	Extension cord from the south	<input checked="" type="checkbox"/>	6/25/2016
	F2	Light cord from the south	<input checked="" type="checkbox"/>	6/25/2016
	G2	Flood light from the Southwest	<input checked="" type="checkbox"/>	6/25/2016
	H2	Flood light from the north	<input checked="" type="checkbox"/>	6/25/2016
	I2	Power pole panel Southwest of area of GOA from the east	<input checked="" type="checkbox"/>	6/25/2016
	J2	I2 panel close up Southwest of GOA from the east	<input checked="" type="checkbox"/>	6/25/2016
	K2	South end GOA pre-grid from the north	<input checked="" type="checkbox"/>	6/26/2016
	L2	GOA pre-grid from the north	<input checked="" type="checkbox"/>	6/26/2016
	M2	GOA pre-grid from the Northwest	<input checked="" type="checkbox"/>	6/26/2016
	N2	GOA pre-grid from the Northeast	<input checked="" type="checkbox"/>	6/26/2016
	O2	GOA pre-grid from the north	<input checked="" type="checkbox"/>	6/26/2016
	P2	GOA pre-grid from the east	<input checked="" type="checkbox"/>	6/26/2016
	Q2	Grid set up pre-grid from the north	<input checked="" type="checkbox"/>	6/26/2016
	R2	Grid set up pre-grid from the east	<input checked="" type="checkbox"/>	6/26/2016
	S2	Post-grid from the north	<input checked="" type="checkbox"/>	6/26/2016
	T2	Post-grid from the east	<input checked="" type="checkbox"/>	6/26/2016
	U2	Grid set up section F from the east	<input checked="" type="checkbox"/>	6/26/2016
	V2	Grid set up section F from the Northeast	<input checked="" type="checkbox"/>	6/26/2016
	W2	Grid set up section F from the Southeast	<input checked="" type="checkbox"/>	6/26/2016
	X2	Branch location on tree from the Northeast	<input checked="" type="checkbox"/>	6/26/2016
	Y2	Branch removal from tree from the Northeast	<input checked="" type="checkbox"/>	6/26/2016
	Z2	South side of tree Specific Origin Area (SOA) pre-grid from the Southeast	<input checked="" type="checkbox"/>	6/26/2016

Case: 16-22831**EVIDENCE AND PHOTOGRAPHIC INFORMATION**

Evidence (Numeric)	Photo (Alpha)	Description of Evidence or Photograph	Format Digital	Date Collected
	A3	South side of tree SOA pre-grid from the Southeast	<input checked="" type="checkbox"/>	6/26/2016
	B3	Grid set up section F from the Northeast	<input checked="" type="checkbox"/>	6/26/2016
	C3	Grid set up section G from the Northeast	<input checked="" type="checkbox"/>	6/26/2016
	D3	Grid set ut section F and G from the east	<input checked="" type="checkbox"/>	6/26/2016
	E3	Grid set ut section F and G from the east	<input checked="" type="checkbox"/>	6/26/2016
	F3	Close up of grid section F and G from the east	<input checked="" type="checkbox"/>	6/26/2016
	G3	Main structure interior breaker panel from the Northeast	<input checked="" type="checkbox"/>	6/27/2016
	H3	Close up main interior breaker panel from the Northeast	<input checked="" type="checkbox"/>	6/27/2016
	I3	Exterior meter and main into the structure from the south	<input checked="" type="checkbox"/>	6/27/2016
	J3	Weather head and main panel into the property from the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	K3	Main breaker from the south	<input checked="" type="checkbox"/>	6/27/2016
	L3	Main breaker from the south	<input checked="" type="checkbox"/>	6/27/2016
	M3	Main structure interior breaker panel from the Northeast	<input checked="" type="checkbox"/>	6/27/2016
	N3	Main structure interior breaker panel from the Northeast	<input checked="" type="checkbox"/>	6/27/2016
	O3	Close up of grid section F and G from the east	<input checked="" type="checkbox"/>	6/27/2016
	P3	Close up of grid section F and G from the east	<input checked="" type="checkbox"/>	6/27/2016
	Q3	Close up of grid section F and G, 4-5 from the south	<input checked="" type="checkbox"/>	6/27/2016
	R3	Close up of grid section F-4 from the south	<input checked="" type="checkbox"/>	6/27/2016
	S3	Close up of grid section G-4 from the south	<input checked="" type="checkbox"/>	6/27/2016
	T3	Close up of grid section G-5 from the south	<input checked="" type="checkbox"/>	6/27/2016
	U3	Close up of grid section F-5 from the south	<input checked="" type="checkbox"/>	6/27/2016
	W3	Close up of grid section F and G, 4-5 from the west	<input checked="" type="checkbox"/>	6/27/2016
	X3	Grid in progress with flaging around SOA from the south	<input checked="" type="checkbox"/>	6/27/2016
	Y3	Grid in progress with flaging around SOA from the east	<input checked="" type="checkbox"/>	6/27/2016
	Z3	Grid in progress with flaging around SOA and flagging from the east	<input checked="" type="checkbox"/>	6/27/2016
	A4	P-1 panel Southeast of the playground from the Southwest	<input checked="" type="checkbox"/>	6/27/2016
	B4	P-1 panel close up Southeast of the playground from the Southwest	<input checked="" type="checkbox"/>	6/27/2016
	C4	P-1 panel close up Southeast of the playground from the Southwest	<input checked="" type="checkbox"/>	6/27/2016
	D4	P-2 with panel south of playground from the east	<input checked="" type="checkbox"/>	6/27/2016

Case: 16-22831

EVIDENCE AND PHOTOGRAPHIC INFORMATION

Evidence (Numeric)	Photo (Alpha)	Description of Evidence or Photograph	Format Digital	Date Collected
	E4	Southeast end of GOA P-2 from the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	F4	Southeast end of GOA P-2 from the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	G4	Southwest side of tree in SOA from the Southwest	<input checked="" type="checkbox"/>	6/27/2016
	H4	Grid in progress with basket ball size SOA grid from the west	<input checked="" type="checkbox"/>	6/27/2016
	I4	Grid in progress with basket ball size SOA inside grid from the west	<input checked="" type="checkbox"/>	6/27/2016
	J4	Grid in progress with flaging around SOA from the west	<input checked="" type="checkbox"/>	6/27/2016
	K4	Grid in progress with flaging around SOA from the south	<input checked="" type="checkbox"/>	6/27/2016
	L4	Grid in progress with flaging around SOA from the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	M4	Grid in progress with flaging around Ignition Area (IA) from the east	<input checked="" type="checkbox"/>	6/27/2016
	N4	Northwest side of tree in SOA from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	O4	North side of tree in SOA from the north	<input checked="" type="checkbox"/>	6/27/2016
	P4	West side of tree in SOA from the west	<input checked="" type="checkbox"/>	6/27/2016
	Q4	Northeast side of tree in SOA from the Northeast	<input checked="" type="checkbox"/>	6/27/2016
	R4	Northeast side top of tree ground level in SOA from the Northeast	<input checked="" type="checkbox"/>	6/27/2016
	S4	Northeast side of tree in SOA from the north east	<input checked="" type="checkbox"/>	6/27/2016
	T4	East side of tree in SOA from the east	<input checked="" type="checkbox"/>	6/27/2016
	U4	Northwest side of interior flagged off area from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	V4	West side of interior flagged off GOA from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	W4	West side of interior flagged off GOA from the west	<input checked="" type="checkbox"/>	6/27/2016
	X4	West side of interior flagged off GOA from the south	<input checked="" type="checkbox"/>	6/27/2016
	Y4	West side of interior flagged off GOA overall from the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	Z4	West side of interior flagged off GOA overall from the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	A5	Center of interior GOA overall from the Southwest	<input checked="" type="checkbox"/>	6/27/2016
	B5	Rear SCE truck into interior GOA from the south	<input checked="" type="checkbox"/>	6/27/2016
	C5	Passenger side SCE truck in GOA area from the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	D5	Passenger side SCE truck in GOA from the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	E5	Passenger side SCE truck out riggers down in GOA from the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	F5	Driver side SCE truck out riggers down inside GOA from the south	<input checked="" type="checkbox"/>	6/27/2016
	G5	Above ground view south half of grid from Northwest	<input checked="" type="checkbox"/>	6/27/2016

Case: 16-22831**EVIDENCE AND PHOTOGRAPHIC INFORMATION**

Evidence (Numeric)	Photo (Alpha)	Description of Evidence or Photograph	Format Digital	Date Collected
	H5	Above ground view north view tree and south half grid from north	<input checked="" type="checkbox"/>	6/27/2016
	I5	Above ground north end grid from the north	<input checked="" type="checkbox"/>	6/27/2016
	J5	Above ground west end of grid and tree from the west	<input checked="" type="checkbox"/>	6/27/2016
	K5	Above ground north view from north	<input checked="" type="checkbox"/>	6/27/2016
	L5	Above ground view north end of grid from the north	<input checked="" type="checkbox"/>	6/27/2016
	M5	Above ground Northeast side top of tree from the Northeast	<input checked="" type="checkbox"/>	6/27/2016
	N5	Above ground Northeast side lower portion of tree/grid from the Northeast	<input checked="" type="checkbox"/>	6/27/2016
	O5	Above ground Northeast side lower portion of tree/grid from the Northeast	<input checked="" type="checkbox"/>	6/27/2016
	P5	Northeast side of tree in SOA above ground view from the Northeast	<input checked="" type="checkbox"/>	6/27/2016
	Q5	Northeast side of tree with power line above ground view from the Northeast	<input checked="" type="checkbox"/>	6/27/2016
	R5	Northeast side of tree with power line above ground view from the Northeast	<input checked="" type="checkbox"/>	6/27/2016
	S5	Northeast side of tree with power line above ground view from the Northeast	<input checked="" type="checkbox"/>	6/27/2016
	T5	Northeast side of tree with power line above ground view from the Northeast	<input checked="" type="checkbox"/>	6/27/2016
	U5	Northeast side of tree with power line above ground view from the Northeast	<input checked="" type="checkbox"/>	6/27/2016
	V5	Northeast side of tree with power line above ground view from the Northeast	<input checked="" type="checkbox"/>	6/27/2016
	W5	Northwest side of tree with power line above ground view from Northwest	<input checked="" type="checkbox"/>	6/27/2016
	X5	Northwest side of tree with power line above ground view from Northwest	<input checked="" type="checkbox"/>	6/27/2016
	Y5	Northwest side of tree with grid above ground view from Northwest	<input checked="" type="checkbox"/>	6/27/2016
	Z5	West side of tree in SOA above ground view from the west	<input checked="" type="checkbox"/>	6/27/2016
	A6	West side lower portion of tree above ground view from the west	<input checked="" type="checkbox"/>	6/27/2016
	B6	West side middle portion of tree above ground view from the west	<input checked="" type="checkbox"/>	6/27/2016
	C6	West side middle portion of tree above ground view from the west	<input checked="" type="checkbox"/>	6/27/2016
	D6	Southwest middle portion of tree above ground view from the east	<input checked="" type="checkbox"/>	6/27/2016
	E6	Southwest side lower portion tree above ground view from west	<input checked="" type="checkbox"/>	6/27/2016
	F6	Southwest side lower portion tree/grid above ground view from west	<input checked="" type="checkbox"/>	6/27/2016
	G6	Southwest side top portion tree above ground view from west	<input checked="" type="checkbox"/>	6/27/2016
	H6	Southwest side top portion tree above ground view from west	<input checked="" type="checkbox"/>	6/27/2016
	I6	Southwest middle portion tree above ground view from west	<input checked="" type="checkbox"/>	6/27/2016
	J6	Southwest top portion tree above ground view from west	<input checked="" type="checkbox"/>	6/27/2016

Case: 16-22831**EVIDENCE AND PHOTOGRAPHIC INFORMATION**

Evidence (Numeric)	Photo (Alpha)	Description of Evidence or Photograph	Format Digital	Date Collected
	K6	Southwest middle portion tree above ground view from west	<input checked="" type="checkbox"/>	6/27/2016
	L6	Southwest middle portion tree above ground view from west	<input checked="" type="checkbox"/>	6/27/2016
	M6	Southwest middle portion tree above ground view from west	<input checked="" type="checkbox"/>	6/27/2016
	N6	Southwest middle portion tree above ground view from west	<input checked="" type="checkbox"/>	6/27/2016
	O6	Northwest middle portion tree above ground view from Northwest	<input checked="" type="checkbox"/>	6/27/2016
	P6	Middle tree main trunk from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	Q6	Northwest middle tree/grid from Northwest	<input checked="" type="checkbox"/>	6/27/2016
	R6	Middle tree from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	S6	Close up middle tree from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	T6	Northwest portion of tree/grid from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	U6	Middle tree from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	V6	Middle tree from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	W6	Middle tree from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	X6	Middle tree from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	Y6	Northeast lower portion tree/grid from the Northeast	<input checked="" type="checkbox"/>	6/27/2016
	Z6	Northeast lower portion tree/grid from the Northeast	<input checked="" type="checkbox"/>	6/27/2016
	A7	Northeast middle tree from the Northeast	<input checked="" type="checkbox"/>	6/27/2016
	B7	Southeast portion of grid from north	<input checked="" type="checkbox"/>	6/27/2016
	C7	Southeast side of tree/grid from the Northeast	<input checked="" type="checkbox"/>	6/27/2016
	D7	Southeast portion of GOA from the north	<input checked="" type="checkbox"/>	6/27/2016
	E7	North portion of GOA from the south	<input checked="" type="checkbox"/>	6/27/2016
	F7	North portion of GOA from the south	<input checked="" type="checkbox"/>	6/27/2016
	G7	North portion of GOA and heel of main fire from the south	<input checked="" type="checkbox"/>	6/27/2016
	H7	North portion of GOA and heel of main fire from the south	<input checked="" type="checkbox"/>	6/27/2016
	I7	Northeast lower portion tree/grid from the Northeast	<input checked="" type="checkbox"/>	6/27/2016
	J7	North portion lower tree/grid from the north	<input checked="" type="checkbox"/>	6/27/2016
	K7	South grid from the east	<input checked="" type="checkbox"/>	6/27/2016
	L7	Northeast portion middle tree/grid from the Northeast	<input checked="" type="checkbox"/>	6/27/2016
	M7	Northeast portion tree from the Northeast	<input checked="" type="checkbox"/>	6/27/2016

Case: 16-22831**EVIDENCE AND PHOTOGRAPHIC INFORMATION**

Evidence (Numeric)	Photo (Alpha)	Description of Evidence or Photograph	Format Digital	Date Collected
	N7	Northeast portion tree from the Northeast	<input checked="" type="checkbox"/>	6/27/2016
	O7	Northeast portion tree from the Northeast	<input checked="" type="checkbox"/>	6/27/2016
	P7	Looking down on the north side of the tree from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	Q7	Middle Northwest section of tree from Northwest	<input checked="" type="checkbox"/>	6/27/2016
	R7	Middle section of tree from the north	<input checked="" type="checkbox"/>	6/27/2016
	S7	Middle section of tree from the north	<input checked="" type="checkbox"/>	6/27/2016
	T7	Middle section of tree with power line from the north	<input checked="" type="checkbox"/>	6/27/2016
	U7	Close up middle section of tree with power line from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	V7	Close up middle section of tree with power line from the north	<input checked="" type="checkbox"/>	6/27/2016
	W7	Close up middle section of tree with power line from the north	<input checked="" type="checkbox"/>	6/27/2016
	X7	Close up middle of tree below power line from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	Y7	Middle section of tree at power line from the north	<input checked="" type="checkbox"/>	6/27/2016
	Z7	Middle section of tree at above power line from the north	<input checked="" type="checkbox"/>	6/27/2016
	A8	Branch above contact with power line from the north	<input checked="" type="checkbox"/>	6/27/2016
	B8	Branch and power line from Northwest	<input checked="" type="checkbox"/>	6/27/2016
	C8	Branch and power line from Northwest	<input checked="" type="checkbox"/>	6/27/2016
	D8	Branch and power line from Northwest	<input checked="" type="checkbox"/>	6/27/2016
	E8	Main branch from Northeast	<input checked="" type="checkbox"/>	6/27/2016
	F8	Main branch looking down from the Northeast	<input checked="" type="checkbox"/>	6/27/2016
	G8	Looking down tree into grid from the Northeast	<input checked="" type="checkbox"/>	6/27/2016
	H8	Looking down east side of tree from the Northeast	<input checked="" type="checkbox"/>	6/27/2016
	I8	Branch above power line from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	J8	Branch and power line from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	K8	Branch and power line from Northwest	<input checked="" type="checkbox"/>	6/27/2016
	L8	Branch below power line from Northwest	<input checked="" type="checkbox"/>	6/27/2016
	M8	Branch and power line from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	N8	Branch and power line from the north	<input checked="" type="checkbox"/>	6/27/2016
	O8	Branch looking down from the north	<input checked="" type="checkbox"/>	6/27/2016
	P8	Branch above power line from the north	<input checked="" type="checkbox"/>	6/27/2016

Case: 16-22831**EVIDENCE AND PHOTOGRAPHIC INFORMATION**

Evidence (Numeric)	Photo (Alpha)	Description of Evidence or Photograph	Format Digital	Date Collected
	Q8	Branch above power line from the north	<input checked="" type="checkbox"/>	6/27/2016
	R8	Branch below power line from the north	<input checked="" type="checkbox"/>	6/27/2016
	S8	Branch below power line from the north	<input checked="" type="checkbox"/>	6/27/2016
	T8	Middle tree below power line looking down from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	U8	Branch above power line looking down from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	V8	Branch above power line looking down from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	W8	Branch above power line looking down from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	X8	Branch at power line looking down from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	Y8	Branch above power line looking down from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	Z8	Branch below power line looking down from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	A9	Branch at power line looking down from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	B9	Branch at power line looking down from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	C9	Branch at power line looking down from north	<input checked="" type="checkbox"/>	6/27/2016
	D9	North side of tree with grid from the north	<input checked="" type="checkbox"/>	6/27/2016
	E9	Indicator Northeast of end of grid from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	F9	Indicators north of SOA from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	G9	P-2 Northeast of SOA from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	H9	Northeast end of GOA from the Southwest	<input checked="" type="checkbox"/>	6/27/2016
	I9	Southeast side of tree from above from the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	J9	South view of tree above from the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	K9	South view top of tree from above from the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	L9	Southwest view from above from the Southwest	<input checked="" type="checkbox"/>	6/27/2016
	M9	Tree with line through it from the Southwest	<input checked="" type="checkbox"/>	6/27/2016
	N9	Lower portion south east of tree from the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	O9	Middle portion south east side of tree from the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	P9	Tree with line through it from the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	Q9	Southeast side of lower portion of tree from the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	R9	Southeast side of tree/grid from Southeast	<input checked="" type="checkbox"/>	6/27/2016
	S9	Southeast side of tree with line from the Southeast	<input checked="" type="checkbox"/>	6/27/2016

Case: 16-22831**EVIDENCE AND PHOTOGRAPHIC INFORMATION**

Evidence (Numeric)	Photo (Alpha)	Description of Evidence or Photograph	Format Digital	Date Collected
	T9	Branch with line from the Southwest	<input checked="" type="checkbox"/>	6/27/2016
	U9	Branch with line from the Southwest	<input checked="" type="checkbox"/>	6/27/2016
	V9	Branch with line from the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	W9	Middle of tree with line from the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	X9	Branch with line from the south	<input checked="" type="checkbox"/>	6/27/2016
	Y9	Lower portion of tree Southeast side from the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	Z9	Branch with line south side of tree from the south	<input checked="" type="checkbox"/>	6/27/2016
	A10	Branch of tree with line close up from the Southwest	<input checked="" type="checkbox"/>	6/27/2016
	B10	Branch of tree with line from the south	<input checked="" type="checkbox"/>	6/27/2016
	C10	Branch of tree with line south side from the south	<input checked="" type="checkbox"/>	6/27/2016
	D10	Branch with line through it close up from the south	<input checked="" type="checkbox"/>	6/27/2016
	E10	Branch with line through it from Southwest	<input checked="" type="checkbox"/>	6/27/2016
	F10	Branch above line from the Southwest	<input checked="" type="checkbox"/>	6/27/2016
	G10	Above look down on line and From the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	H10	Middle section south side looking down from line from south	<input checked="" type="checkbox"/>	6/27/2016
	I10	Middle section of tree looking down into grid from the south	<input checked="" type="checkbox"/>	6/27/2016
	J10	Branch below line showing Southwest side from the Southwest	<input checked="" type="checkbox"/>	6/27/2016
	K10	Close up branch below line Southwest side from the Southwest	<input checked="" type="checkbox"/>	6/27/2016
	L10	Close up branch above line Southwest side from the Southwest	<input checked="" type="checkbox"/>	6/27/2016
	M10	Branch with line showing in L10 from the Southwest	<input checked="" type="checkbox"/>	6/27/2016
	N10	Branch with line from the south	<input checked="" type="checkbox"/>	6/27/2016
	O10	Secondary branch below line contact from the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	P10	Branch just below line contact from the south	<input checked="" type="checkbox"/>	6/27/2016
	Q10	Branch at line contact from the south	<input checked="" type="checkbox"/>	6/27/2016
	R10	Line close up at tree contact from the south	<input checked="" type="checkbox"/>	6/27/2016
	S10	South side of branch above line contact from the south	<input checked="" type="checkbox"/>	6/27/2016
	T10	South east side of branch above line contact from ths Southeast	<input checked="" type="checkbox"/>	6/27/2016
	U10	Middle of tree looking into grid from the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	V10	Main branch just under line level from Southeast	<input checked="" type="checkbox"/>	6/27/2016

EVIDENCE AND PHOTOGRAPHIC INFORMATION

Evidence (Numeric)	Photo (Alpha)	Description of Evidence or Photograph	Format Digital	Date Collected
	W10	Branch with line dug in from the Southwest	<input checked="" type="checkbox"/>	6/27/2016
	X10	Close up of W10 from Southwest	<input checked="" type="checkbox"/>	6/27/2016
	Y10	Over all tree branches removed to access line from the Northeast	<input checked="" type="checkbox"/>	6/27/2016
	Z10	Over all tree branches removed to access line from the east	<input checked="" type="checkbox"/>	6/27/2016
	A11	Middle tree branches removed to access line from the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	B11	Southeast view of tree branches removed from the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	C11	Middle tree branches removed from the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	D11	Middle tree branches removed from the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	F11	Middle tree branches removed from the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	G11	Middle tree branches removed from the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	H11	Line being set up for removal from the east	<input checked="" type="checkbox"/>	6/27/2016
	I11	Line cut branches taped for removal from the north	<input checked="" type="checkbox"/>	6/27/2016
	J11	Branch cut with line removed from the north	<input checked="" type="checkbox"/>	6/27/2016
	K11	Grid SOA from the east	<input checked="" type="checkbox"/>	6/27/2016
	L11	Grid Ignition Area (IA) from the east	<input checked="" type="checkbox"/>	6/27/2016
	M11	Grid IA from Southwest	<input checked="" type="checkbox"/>	6/27/2016
	N11	Grid IA from the south	<input checked="" type="checkbox"/>	6/27/2016
	O11	Close up of IA from the Southwest	<input checked="" type="checkbox"/>	6/27/2016
	P11	Direct over head of IA from the south	<input checked="" type="checkbox"/>	6/27/2016
	Q11	E-1 overall from the south	<input checked="" type="checkbox"/>	6/27/2016
	R11	E-1 close up with 2B marker	<input checked="" type="checkbox"/>	6/27/2016
	S11	E-2 overall from the east	<input checked="" type="checkbox"/>	6/27/2016
	T11	E-2 close up with 1B marker	<input checked="" type="checkbox"/>	6/27/2016
	U11	E-3 over all from the south west	<input checked="" type="checkbox"/>	6/27/2016
	V11	Northeast end of GOA from the north	<input checked="" type="checkbox"/>	6/27/2016
	W11	North end of GOA from the north	<input checked="" type="checkbox"/>	6/27/2016
	X11	Northwest end GOA island from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	Y11	Middle of GOA from the north	<input checked="" type="checkbox"/>	6/27/2016
	Z11	Middle east GOA from the Northeast	<input checked="" type="checkbox"/>	6/27/2016

Case: 16-22831**EVIDENCE AND PHOTOGRAPHIC INFORMATION**

Evidence (Numeric)	Photo (Alpha)	Description of Evidence or Photograph	Format Digital	Date Collected
	A12	Middle west of GOA from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	B12	Middle of GOA overall from the north	<input checked="" type="checkbox"/>	6/27/2016
	C12	East side middle GOA from the Northeast	<input checked="" type="checkbox"/>	6/27/2016
	D12	Middle section of GOA west side from the north	<input checked="" type="checkbox"/>	6/27/2016
	E12	Middle GOA west side from the Northeast	<input checked="" type="checkbox"/>	6/27/2016
	F12	West side of GOA facing SOA from the Northeast	<input checked="" type="checkbox"/>	6/27/2016
	G12	West side of GOA facing SOA from the west	<input checked="" type="checkbox"/>	6/27/2016
	H12	G12 Lateral indicator from the west	<input checked="" type="checkbox"/>	6/27/2016
	I12	G12 indicator from the east	<input checked="" type="checkbox"/>	6/27/2016
	J12	Advancing indicators middle west side of GOA from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	K12	Advancing indicator middle west side of GOA from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	L12	K12 close up Northwest side from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	M12	K12 close up from Southeast	<input checked="" type="checkbox"/>	6/27/2016
	N12	Advancing indicators middle of GOA from the north	<input checked="" type="checkbox"/>	6/27/2016
	O12	N12 indicators from the south	<input checked="" type="checkbox"/>	6/27/2016
	P12	N12 indicators from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	Q12	Lateral indicators middle east side of GOA from the Northeast	<input checked="" type="checkbox"/>	6/27/2016
	R12	Q12 indicators from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	S12	Q12 indicators close up from west	<input checked="" type="checkbox"/>	6/27/2016
	T12	Q12 indicators from east	<input checked="" type="checkbox"/>	6/27/2016
	U12	Advancing indicators middle west side facing grid from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	V12	U12 close up from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	W12	U12 close up from the Southwest	<input checked="" type="checkbox"/>	6/27/2016
	X12	Advancing indicators middle west side facing grid from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	Y12	X12 close up from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	Z12	X12 close up from Northeast	<input checked="" type="checkbox"/>	6/27/2016
	A13	Advancing indicator center GOA facing grid from the north	<input checked="" type="checkbox"/>	6/27/2016
	B13	A13 from the south	<input checked="" type="checkbox"/>	6/27/2016
	C13	A13 from the north	<input checked="" type="checkbox"/>	6/27/2016

Case: 16-22831**EVIDENCE AND PHOTOGRAPHIC INFORMATION**

Evidence (Numeric)	Photo (Alpha)	Description of Evidence or Photograph	Format Digital	Date Collected
	D13	Lateral indicator Northeast of corner of grid from the Northeast	<input checked="" type="checkbox"/>	6/27/2016
	E13	Lateral indicator Northeast of corner of grid from the Northeast	<input checked="" type="checkbox"/>	6/27/2016
	F13	D13/14 indicator from the north	<input checked="" type="checkbox"/>	6/27/2016
	G13	D13/14 indicator from the west	<input checked="" type="checkbox"/>	6/27/2016
	H13	Lateral and advancing indicators facing grid from the east	<input checked="" type="checkbox"/>	6/27/2016
	I13	H13 lateral indicator close up from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	J13	H13 indicator close up from the east	<input checked="" type="checkbox"/>	6/27/2016
	K13	Lateral indicator facing the grid from the east	<input checked="" type="checkbox"/>	6/27/2016
	L13	K13 indicator from the east	<input checked="" type="checkbox"/>	6/27/2016
	M13	K13 indicator from the west	<input checked="" type="checkbox"/>	6/27/2016
	N13	Backing indicator Southeast from grid from the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	O13	N13 close up from the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	P13	N13 from the north	<input checked="" type="checkbox"/>	6/27/2016
	Q13	Backing indicators south end of the GOA facing the grid from the Southwest	<input checked="" type="checkbox"/>	6/27/2016
	R13	Q13 close up from the Southwest	<input checked="" type="checkbox"/>	6/27/2016
	S13	Q13 close up from the north	<input checked="" type="checkbox"/>	6/27/2016
	T13	Backing indicators Southwest from the grid from the Southwest	<input checked="" type="checkbox"/>	6/27/2016
	U13	T13 indicator from the Southwest	<input checked="" type="checkbox"/>	6/27/2016
	V13	T13 indicator from the Northeast	<input checked="" type="checkbox"/>	6/27/2016
	W13	Backing and item of interest indicators Southwest side of GOA from Southwest	<input checked="" type="checkbox"/>	6/27/2016
	X13	W13 item of interest from the west	<input checked="" type="checkbox"/>	6/27/2016
	Y13	Comparison item of interest from the south	<input checked="" type="checkbox"/>	6/27/2016
	Z13	Close up comparison item close up from the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	A14	Porta potties Northwest of grid from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	B14	A14 from the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	C14	South end of the GOA over all from the south	<input checked="" type="checkbox"/>	6/27/2016
	D14	South end of the GOA from the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	E14	Southeast end of GOA from the east	<input checked="" type="checkbox"/>	6/27/2016
	F14	Items of interest center of the north end GOA from the north	<input checked="" type="checkbox"/>	6/27/2016

Case: 16-22831**EVIDENCE AND PHOTOGRAPHIC INFORMATION**

Evidence (Numeric)	Photo (Alpha)	Description of Evidence or Photograph	Format Digital	Date Collected
	G14	Lighter from the north	<input checked="" type="checkbox"/>	6/27/2016
	H14	G14 from the south	<input checked="" type="checkbox"/>	6/27/2016
	I14	G14 from the south east back side	<input checked="" type="checkbox"/>	6/27/2016
	J14	Item of intrest north end of the GOA from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	K14	J14 from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	L14	Plastic container with rocks from the south	<input checked="" type="checkbox"/>	6/27/2016
	M14	Plastic container back side from the south	<input checked="" type="checkbox"/>	6/27/2016
	N14	Grid from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	O14	Grid from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	P14	Grid from the north	<input checked="" type="checkbox"/>	6/27/2016
	Q14	Grid from Northeast	<input checked="" type="checkbox"/>	6/27/2016
	R14	Grid from the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	S14	Grid from the south	<input checked="" type="checkbox"/>	6/27/2016
	T14	IA from the south	<input checked="" type="checkbox"/>	6/27/2016
	U14	E-3 overall from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	V14	E-3 from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	W14	E-3 from the west	<input checked="" type="checkbox"/>	6/27/2016
	X14	E-3 from the Southwest	<input checked="" type="checkbox"/>	6/27/2016
	Y14	E-3 from the east	<input checked="" type="checkbox"/>	6/27/2016
	Z14	E-3 from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	A15	E-3 from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	B15	E-3 from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	C15	E-3 from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	D15	E-3 from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	E15	E-3 from the north	<input checked="" type="checkbox"/>	6/27/2016
	F15	E-3 from the north	<input checked="" type="checkbox"/>	6/27/2016
	G15	E-3 from the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	H15	E-3 from the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	I15	E-3 from the south	<input checked="" type="checkbox"/>	6/27/2016

Case: 16-22831**EVIDENCE AND PHOTOGRAPHIC INFORMATION**

Evidence (Numeric)	Photo (Alpha)	Description of Evidence or Photograph	Format Digital	Date Collected
	J15	E-3 from the south	<input checked="" type="checkbox"/>	6/27/2016
	K15	E-3 from the south	<input checked="" type="checkbox"/>	6/27/2016
	L15	E-3 from the Northeast	<input checked="" type="checkbox"/>	6/27/2016
	M15	E-3 from the north	<input checked="" type="checkbox"/>	6/27/2016
	N15	E-3 from the north	<input checked="" type="checkbox"/>	6/27/2016
	O15	E-3 from the Northeast	<input checked="" type="checkbox"/>	6/27/2016
	P15	E-3 from the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	Q15	E-3 from the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	R15	E-3 from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	S15	E-3 from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	T15	E-3 from the north	<input checked="" type="checkbox"/>	6/27/2016
	U15	E-3 from the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	V15	E-3 from the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	W15	E-3 from the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	X15	E-3 from the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	Y15	E-3 from the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	Z15	E-3 from the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	A16	E-3 from the north	<input checked="" type="checkbox"/>	6/27/2016
	B16	E-3 from the north	<input checked="" type="checkbox"/>	6/27/2016
	C16	E-3 from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	D16	E-3 from the Northwest	<input checked="" type="checkbox"/>	6/27/2016
	E16	E-3 from the south	<input checked="" type="checkbox"/>	6/27/2016
	F16	E-3 from the Southeast	<input checked="" type="checkbox"/>	6/27/2016
	G16	E-4 and E-5 from the north	<input checked="" type="checkbox"/>	6/28/2016
	H16	E-4 from the Northeast	<input checked="" type="checkbox"/>	6/28/2016
	I16	E-5 from the Northwest	<input checked="" type="checkbox"/>	6/28/2016
	J16	E-4 collected from the Northeast	<input checked="" type="checkbox"/>	6/28/2016
	K16	E-5 collected from the Northwest	<input checked="" type="checkbox"/>	6/28/2016
	L16	Scene overall from the Northwest	<input checked="" type="checkbox"/>	6/28/2016

