



Kolmakof Mine Site RSI SOW - Map and Photos




Kolmakof Mine Site location



Kolmakof Mine Site area photo



Mill Area looking South toward the river



Camp Area looking North. Location of key features are noted though not all are visible in the photo.



Collapsing Ball Mill. Surface water is passing under the debris.



Mercury flasks in shed next to Ball Mill – This building possibly held a retort.



Remains of the “dynamite” shed on 8/18/2006. Shed was burned-down in 2000.



Photo of “dynamite” inside the shed, June 2000. Deteriorated explosives are on the ground and full cases are seen in the background resting on an empty Blazo can.



Pond near the Ball Mill. Cloudy water is probably due to heavy rains on the day of and prior to the inspection. This pond is located about 10-15 feet from the Ball Mill. The hillside in the background is likely man-made – tails or waste rock.



Derelict truck near the Ball Mill.



Beer Keg device at the suspected retort facility near the Camp Area



Firebrick lined pit at the suspected Camp Area retort facility.



Low concrete and brick wall with a hearth-door? at suspected Camp Area retort facility.



Piles of drums. Numerous piles like this are scattered in the general vicinity of the suspected Camp Area retort facility. All drums inspected were empty with no sign of spills.



Interior condition of two of the three cabins





Wall tent in the Camp Area. Bottom photo is the interior.





This cabin may have been the “Mine Manager’s House”. Interior view below.

