

**D**

**Photographs**

CONTACT AND SONOMA MERCURY MINES  
Sonoma County, California



Photo 1 Retort located at Sonoma near well 04SM-MW.

---

*Direction: Northwest*

*Photographed By: Andrew Uhrig*

---



Photo 2 Retort located at Sonoma near well 04SM-MW.

---

*Direction: South*

*Photographed By: Bryan Ciecko*

---

CONTACT AND SONOMA MERCURY MINES  
Sonoma County, California



Photo 3 Looking down-gradient from well 04SM-MW.

---

*Direction: Southeast*

*Photographed By: Andrew Uhrig*

---

CONTACT AND SONOMA MERCURY MINES  
Sonoma County, California



Photo 4 Drilling well 07CM-MW at Contact Mine.

---

*Direction: Southeast*

*Photographed By: Andrew Uhrig*

---

CONTACT AND SONOMA MERCURY MINES  
Sonoma County, California



Photo 5 Seep coming from drainage adit near well 07CM-MW at Contact Mine.

---

*Direction: Southeast*

*Photographed By: Andrew Uhrig*

---

CONTACT AND SONOMA MERCURY MINES  
Sonoma County, California



Photo 6 Seep coming from drainage adit near well 07CM-MW at Contact Mine.

---

*Direction: Southeast*

*Photographed By: Andrew Uhrig*

---

CONTACT AND SONOMA MERCURY MINES  
Sonoma County, California



Photo 7 Toe of tailings pile (04SM-SB) that is migrating down-slope at Contact Mine.

---

*Direction: Northeast*

*Photographed By: Andrew Uhrig*

---

CONTACT AND SONOMA MERCURY MINES  
Sonoma County, California



Photo 8 A mixture of tailings and native material in roadcut at Contact Mine.

---

*Direction: Northeast*

*Photographed By: Andrew Uhrig*

---



Photo 9 Borehole for well 05CM-MW.

---

*Direction: West*

*Photographed By: Andrew Uhrig*

---

CONTACT AND SONOMA MERCURY MINES  
Sonoma County, California



Photo 10 Drainage adit near well 07CM-MW at Contact Mine.

---

*Direction: Northeast*

*Photographed By: Andrew Uhrig*

CONTACT AND SONOMA MERCURY MINES  
Sonoma County, California



Photo 11 Water flowing from drainage adit near well 07CM-MW at Contact Mine.

---

*Direction: Northeast*

*Photographed By: Andrew Uhrig*

---

CONTACT AND SONOMA MERCURY MINES  
Sonoma County, California




Photo 12 View to the northwest of lower drainage adit, 07CM-MW, 06CM-SB and 05CM-MW at Contact Mine.

---

*Direction: Northwest*

*Photographed By: Andrew Uhrig*

---




Photo 13 The road grade across the valley connects the Contact and Sonoma mines, west from Contact.

---

*Direction: West*

*Photographed By: Andrew Uhrig*

---

CONTACT AND SONOMA MERCURY MINES  
Sonoma County, California



Photo 14 The road grade across the valley connects the Contact and Sonoma mines, southwest from Contact.

---

*Direction: Southwest      Photographed By: Andrew Uhrig*

---



Photo 15 Sonoma mine from Contact mine.

---

*Direction: South      Photographed By: Andrew Uhrig*

---

CONTACT AND SONOMA MERCURY MINES  
Sonoma County, California



Photo 16 Sonoma mine from Contact mine.

---

*Direction: South*

*Photographed By: Andrew Uhrig*

---




Photo 17 Shed located along old road between Contact and Sonoma mines.

---

*Direction: West*

*Photographed By: Andrew Uhrig*

---

CONTACT AND SONOMA MERCURY MINES  
Sonoma County, California



Photo 18 Sonoma mine looking southeast. Bare soil in the mid-ground is the flat associated with 02SM-SB. The equipment in the background is located on the flat associated with 08SM-SB.

*Direction: Southeast*

*Photographed By: Andrew Uhrig*



Photo 19 View of Contact from Sonoma, looking north. The lighter green areas are areas most likely influenced by mining activities. The light red-brown pile in the middle of the photo is the tailings pile at Contact associated with boring 04CM-SB.

*Direction: North*

*Photographed By: Andrew Uhrig*

CONTACT AND SONOMA MERCURY MINES  
Sonoma County, California




Photo 20 Zoomed in view similar to 064.

---

*Direction: North*

*Photographed By: Andrew Uhrig*

---




Photo 21 Zoomed in view similar to 064 and 067.

---

*Direction: North*

*Photographed By: Andrew Uhrig*

---

CONTACT AND SONOMA MERCURY MINES  
Sonoma County, California



Photo 22 Soil cuttings from 05SM-SB B (foreground) and D-retort (Background).

---

*Direction: West*

*Photographed By: Bryan Ciecko*

---

CONTACT AND SONOMA MERCURY MINES  
Sonoma County, California




Photo 23 Top of calcine/tailings pile near 03CM-MW and 04CM-SB.

---

*Direction: Southwest*

*Photographed By: Bryan Ciecko*

---

CONTACT AND SONOMA MERCURY MINES  
Sonoma County, California



Photo 24 Drilling borehole 02CM-SB.

---

*Direction: Northeast*

*Photographed By: Bryan Ciecko*

---

CONTACT AND SONOMA MERCURY MINES  
Sonoma County, California




Photo 25 Drilling borehole 02CM-SB.

---

*Direction: Southwest*

*Photographed By: Bryan Ciecko*

---



Photo 26 Dealing with muddy conditions near 03CM-MW.

---

*Direction: Southeast*

*Photographed By: Bryan Ciecko*

---

CONTACT AND SONOMA MERCURY MINES  
Sonoma County, California



Photo 27 Dealing with muddy conditions near 03CM-MW.

---

*Direction: Southeast*

*Photographed By: Bryan Ciecko*

---



Photo 28 Power Augering at location 04SM-MW.

---

*Direction: West*

*Photographed By: Bryan Ciecko*

---

CONTACT AND SONOMA MERCURY MINES  
Sonoma County, California



Photo 29 Drilling borehole 04CM-SB.

---

*Direction: Southwest*

*Photographed By: Bryan Ciecko*

---

CONTACT AND SONOMA MERCURY MINES  
Sonoma County, California



Photo 30 Metal pipe above retort 1 at Sonoma Mine.

*Direction: North*

*Photographed By:*



Photo 31 Debris on the concrete pad at the location of retort 2 at Sonoma Mine.

*Direction: West*

*Photographed By:*