

CO-060-027 Photos



Closed Route off 3136
Direction: West



View from 3136
Direction: North West



3136a, as seen from 3136
Needs to be cleared
Direction: North East



Road improvement (culvert pipe under rocks) on 3136
Direction: West



Closed Route off 3136
Direction: East



Old logging roads and stumps visible from 3136
Direction: West



3136 in need of maintenance
Direction: South



Logging road/stumps off 3136
Direction: East



View of 3136b from 3136
Direction: East



Closed Route off 3136
Direction: North



End of 3136
Direction: West



View into CO-060-027
Direction: North



Down tree on 3049d
Direction: North West



View from 3049d
Direction: North



View from 3049d
Direction: South West



Closed Route off 3049d
Direction: East / South East



Closed Route off 3049d
Direction: North West



Road improvement (water drainage ditch) on 3049d



Road improvement (water drainage ditch) 3049d



Stumps/logging roads off 3049d
Direction: East



End of 3049d
Direction: North East



View of 3049b
Direction: West



Closed Road off 3049b
Direction: North



Road not on map off 3049b
Direction: North



View from end of 3049b
Direction: North East



3049b rocky road
Direction: West



View of 3049c
Direction: North



View from end of 3049c
Direction: North



View of 3050
Direction: North