



Context Photograph

Summary of Visual Changes

Type/Sensitivity of Users: Residential community; high sensitivity to visual quality

Volume of Users: Low - small community

T/L Distance from Viewer: Middleground - one-half to one mile

T/L Prominence in Landscape: Low - closely backdropped by hills

Existing Modifications: Existing wood pole transmission line and scattered residential and ranching structures.

Contrast rating: Moderate

VRM Class: IV

Visual Impact Rating: Medium

KOP 3 Crescent Valley

Figure 3.9-4

Falcon to Gonder Project EIS