

Watershed Health Standard 1-Upper Muddy Creek Section



Page 7-1 Muddy Creek Headwaters



Page 7-2 Muddy Creek within Incised Banks



Page 8-1 Muddy Creek, C-6 channel type

Watershed Health Standard 1-Upper Muddy Creek Section



Page 8-2 Muddy Creek, E-6 channel type



Page 8-3
Littlefield Creek, B-4 channel type



Page 8-4 Muddy Creek at George Dew wetlands, D-6 channel type



Watershed Health Standard 1-Upper Muddy Creek Section



Page 8-5 Cattle using Muddy Creek watershed



Page 8-6 Soil erosion, lack of wing-ditching



Page 8-7 Road caused soil erosion into Little Muddy Creek

Watershed Health Standard 1-Upper Muddy Creek Section



Page 9-1 Natural gas development by BP America




Page 9-2 Beaver activity in Muddy Creek



Watershed Health Standard 1-Upper Muddy Creek Section



Page 10-1 Sulphur Springs, Muddy Creek, late 1800s



Page 10-2 Sulphur Springs, Muddy Creek, 1996

Watershed Health Standard 1-Upper Muddy Creek Section



Page 12-1 Soil erosion, two-track roads



Page 12-2 Waterbar along Muddy Creek road




Page 12-3 Gradient control along Muddy Creek



Watershed Health Standard 1-Upper Muddy Creek Section



Page 12-4 Littlefield Creek, Sulphur Springs allotment, 1989



Page 12-5 Littlefield Creek, Sulphur Springs allotment, 2000

Watershed Health Standard 1-Upper Muddy Creek Section



Page 12-6 Muddy Creek, Doty Mountain Allotment, 1989



Page 12-7 Muddy Creek, Doty Mountain Allotment, 2000

Watershed Health Standard 1-Upper Muddy Creek Section



Page 12-8 New culvert crossing at Littlefield Creek



Page 12-9 New drop-pipe in road along Muddy Creek

Watershed Health Standard 1-Upper Muddy Creek Section



Page 13-1
Soil erosion at George Dew wetlands, 1992



Page 13-2 Repaired spreader dike, George Dew wetlands, 2002



Page 13-3 Winter cattle use at George Dew wetlands

Watershed Health Standard 1-Barrel Springs Draw Section



Page 13-4 Landscape overview of Barrel Springs Draw



Page 13-5 Overview of Lower Barrel Springs Draw and the Flattops



Page 14-1 North Barrel Springs Draw

Watershed Health Standard 1-Barrel Springs Draw Section



Page 14-2 Lower Barrel Springs Draw



Page 14-3 Natural gas drilling rig



Page 16-1 Roadside erosion, lack of culverts and wing-ditching

Watershed Health Standard 1-Barrel Springs Draw Section



Page 16-2 Gully erosion below culvert



Page 16-3 Poor gas pad reclamation



Page 16-4 Good gas pad reclamation

Watershed Health Standard 1-Lower Muddy Creek Section



Page 17-1 Landscape overview of Lower Muddy Creek



Page 17-2 Foothills, Upper Wild Cow Creek



Watershed Health Standard 1-Lower Muddy Creek Section



Page 18-1 Wild Cow Creek, C-6 stream type



Page 18-2 Cow Creek, E-6 stream type



Watershed Health Standard 1-Lower Muddy Creek Section



Page 18-3 Muddy Creek in East Muddy allotment, spring grazing



Page 18-4 Muddy Creek in Cherokee allotment, summer through fall grazing



Watershed Health Standard 1-Lower Muddy Creek Section



Page 20-1 Upland spreader dikes, constructed in 1950s for watershed protection



Page 20-2 Contour furrows and wheatgrass seeding, constructed in 1950s



Page 20-3 Decadent aspen stand

Watershed Health Standard 1-Lower Muddy Creek Section



Page 20-4 Newly gravelled gas field road



Page 20-5
Culvert erosion in Cottonwood Creek drainage



Page 21-1 Poor gas pad reclamation



Watershed Health Standard 1-Savery Creek Section



Page 21-2 Overview of upper Savery Creek



Page 21-3 Overview of Savery Creek



Watershed Health Standard 1-Savery Creek Section



Page 22-1 Little Savery Creek, C-4 stream type



Page 22-2 Hells Canyon Creek, B-4 stream type



Watershed Health Standard 1-Savery Creek Section



Page 23-1 Loco Creek, Morgan-Boyer allotment, 1992



Page 23-2 Loco Creek, Morgan-Boyer allotment, 2000



Watershed Health Standard 1-Savery Creek Section



Page 24-1 Two-track erosion along Continental Divide Trail



Page 24-2 Sediment added to Little Savery Creek, McCarty Canyon

Watershed Health Standard 1-Little Snake River- Willow Creek and Powder Wash Section



Page 24-3 Landscape view of Cottonwood Creek across to Muddy Mountain



Page 24-4 Landscape view of west end of Powder Rim

Watershed Health Standard 1-Little Snake River- Willow Creek and Powder Wash Section



Page 26-1 Powder Wash road erosion, lack of wing-ditching



Page 27-1 Cattle use along Cottonwood Creek in Cherokee allotment



Watershed Health Standard 1-Sand Creek-Upper and Lower Sections



Page 27-2 Landscape view of Powder Rim across to Adobetown Wilderness Study Area



Page 27-3 Adobetown badlands



Watershed Health Standard 1-Sand Creek-Upper and Lower Sections



Page 28-1 Overview of lower Sand Creek



Page 28-2 Sand Creek, D-5 stream type



Page 28-3 Landscape view of Hangout Draw and south side of Flattops

Watershed Health Standard 1-Sand Creek-Upper and Lower Sections



Page 28-4 Wild horses along Sand Creek



Page 29-1 Road erosion, lack of wing-ditching



Watershed Health Standard 1-Sand Creek-Upper and Lower Sections



Page 29-2 New road from seismic testing



Page 30-1 Damaged cattleguard and braces



Watershed Health Standard 1-Shell Creek Section



Page 31-1 Landscape view of Shell Creek watershed



Page 31-2 Shell Creek, C-6 stream type

